

Container Supervision Report

General Information:



Client name:

Main products and HS code:

polystone decoration 392640 garden decoration 392640 acrylic craft 392640 metal craft 830629 lucky gifts 630491

fashion accessories 392640, 711620

glassware 700200 displays 732690 plastic printings 392640 key-rings 732690 home decoration 830629

Loading location:

Container loading date:

Expected Shipment Date:

Actul Shpment Date:

P/O or P/I number:

Supplier:

Yiwu port

2013.11.29

2013.12.02

LC0020131108

Supplier:

Order summary: good

Total G.W.: 5813kg Total Volume: 27m3 Total Cartons: 282

Important notes:

Loading conditions customer required:

N/A

Conclusion of loading:

The loading worker is skilled and professional, Everything is OK, except 2CBM space left



A.INSPECTION RESULT SUMMARY					
	Result	Findings/Remarks			
Defectives list			CRITICAL	MAJOR	MINOR
		Found		N/A	
	Within AQL	Max	N/A	N/A	N/A
		Checked		N/A	
		Most serious defects found: 0			
Test result	Passed	ok			
Quantity	N/A	OK			
Shipping marks	OK	LAN			

B.INSPECTION RESULT SUMMARY		
Inspection type	Container Loading Check (CLC)	
Sampling standard	ISO 2859-1 (Mil Std 105E)	
Sampling level	S3	
AQL for Critical defective	Not Allowed	
AQL for Major defective	2.5	
AQL for Minor defective	4	
Sampling size for Cri/Maj/Min	N/A	
No. of inspected pieces	N/A	
Total quantity of cartons in your shipment	N/A	
Quantity of cartons available for inspection	N/A	
No. of cartons inspected	N/A	

REMARKS	
	NI/A
	N/A



	Zanos ereap zimitea// in righte reserve				
C.LOADING QTY & PACKING REQUIREMENTS					
C.1	Loaded Quantity				
Expected Result Res		sult	Actual Finding / Comments		
Total no. of Container(s) ok loaded: 20FT GP:1		k	1 20ft GP container		
Total no. of cartons (Bags) ok loaded :282ctns		k	282ctns		
Numbering 300)	g of cartons: (1 to	ok		N/A	
C.2 Loaded Package Summary					
Bags		19BAGS			
Normal Cartons		263CTNS			
Wooden support		N/A			
Pallets		N/A			
Other packages		N/A			
C.3 Heavy cargo, light cargo, fra			gile, irre	gular cargo	
Heavy cargo:		bottom			
Light cargo:		upside			
Fragile:		paste fragile mark			
Irreegular:		special support			
0 4 5 5 5 4 4					

C.4 Cartons,Bags,Pallets details

Cartons and Bags Pictures In warehouse





C.5 Shipping Marks

Expected Result	Result	Actual Finding / Comments
a. Carton Front Mark	OK	Refer to below picture



b.Carton Side Mark

OK

Refer to below picture

D.LOADING PROCESS			
D.1	Empty Container		
Requested Check		Actual Finding / Comments	
- Water - Rust hole - Dust - Grease - General	general conditions: es cleanliness need dryer	Overall container condition is good and free from: - Water - Rust holes - Dust - Grease - General cleanliness - Dry weather, no need dryer	
Container	seal numbers	UBK27705	
Inside con	tainer numbers	KKTU 75783222G1	
Outside container numbers		KKTU 75783222G1	
Pictures As bellow			





No

Did any cartons fall on the floor during

loading?



Pictures As bellow





1/4 Full Container

take by hand and trolley





Start from Back

By hand

D.2 **1/2 Full Container**

Requested Check			
Did any cartons fall on the floor during			
loading?			

Actual Finding / Comments





1/2 Full container

1/2 Full container

NO



D.3	Full Container		
	Requested Check	Actual Finding / Comments	
Is the container completely full? If no, describe how cartons are tied together.		No	
	ny space between the top of the of cartons and the roof of the?	No, the space left is about 1.63m(W)0.75m(H)	
Did any cartons fell on the floor during loading?		No	

Pictures





Full container loaded

Container(s) seals number





The left space

D.4	Container closing	
	Requested Check	Actual Finding / Comments
Are seals t	emporary or definitive?	Definitive







Closing the Door

Closed







Finished

E.IMPORTANT NOTES

THE ABOVE RESULT(S) REFLECT(S) LANCE GROUP LIMITED'S FINDINGS AT THE TIME AND PLACE OF INSPECTION. THIS REPORT DOES NOT RELEASE THE BUYER OR SELLER FROM CONTRACTUAL RESPONSIBILITIES, NOR DOES IT PREJUDICE THE BUYER'S RIGHT OF CLAIM TOWARD THE SELLER/SUPPLIER FOR COMPENSATION FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING INSPECTION OR OCCURRING ANYTIME THEREAFTER.

THE END OF REPORT