

Pre-shipment Inspection Report

PRODUCT DESCRIPTION:						
	Client Name:	CSDP				
	Product Name:	BOOKENDS				
	Inspection Location	YIWU				
	PO Number:	4172				
	Factory Name:	GUANG DONG MING QIANG STATIONERY FACTORY				
	Order Quantity:	16000PCS				
	Quantity ready for inspection:	15921PCS				
	Reference sample available:	YES				

	Passed		
OVERALL INSPECTION RESULT:	(Client has the final decision to Reject or Approve)		

A.INSPECTION RESULT SUMMARY						
	Result		Findings,	/Remarks		
			CRITICAL	MAJOR	MINOR	
		Found	0	6	6	
		Max	0	10	14	
WORKMANSHIP	Within AQL	Checked	500	500	500	
(Defectives list)						
Quantity	ok	Su	pplier produ	ices 15921p	DCS.	
Style	ok					
Colors	ok					
Dimensions & Weight	ok					
Packing&Packging	ok	Each carton is packed with 2 boxes, bo double corrugated.		xes, both		
Shipping marks	ok					



OTHER REMARKS

1. We have the blue sample which you approved before production.


2. Each carton is packed with 2 boxes, both double corrugated, each carton is less than 20KG.

- 3. Total qty is 15921pcs, not 16000pcs as client ordered.
- 4. Extra carton of OPP bag for client to replace in Italy.

B INSDECTION STANDADDS

PSI
ISO 2859-1 (Mil Std 105E)
III
Not Allowed
1
1.5
500/500/500
500
799
799
26

C.INSPECTORS



D.QUALITY CRITERIA						
D.1	Quantity					
Expected Result		Result	Actual Finding / Comments			
		ok	100% goods were finished and packed into export carton, total 15921pcs.			

	NCE GRO Inline Order Co www.linkyiwu.	ntrol		Lance	Group Lim	ited,All righ	ts reserved
Item No.	Total Quantity	Item No.	Total Quantity	Item No.	Total Quantity	Item No.	Total Quantity
4172/557 8	3779pcs	4172/557 9	4098pcs	4172/558 0	3978pcs	4172/558 1	4066pcs
D.2	Bookends	s Style					
Ex	pected Res	sult	Result	Act	Actual Finding / Comments		
The sam	e as client's	artwork					
			ok	Please check below pictures			res
2004 2004							
D.3 Colors							
Ex	pected Res	sult	Result	Acti	ual Finding	g / Comme	ents
ATWORK Regilibro sagomati		2200	ok	Election		CORRECT OF THE OFFICE	



ADE IN CLIMA		TER-PERO
Made Made In Shine		
D.4 Dimensions & Weig		
Expected Result	Result	Actual Finding / Comments
The same as approved samples	ok	Pls see below info and Part III
4172/5578: 175*119*200MM	ok	175*119*200MM
4172/5579:120*119*200MM	ok	120*119*200MM
4172/5580:127*119*200MM	ok	127*119*200MM
4172/5581:172*119*200MM	ok	172*119*200MM
D.5 Packaging		



Unit Packing

Unit Packing					
Expected Result	Result	Actual Finding / Comments			
	ok				
MADE IN CHINA	ОК	MARIENTI ACTIVA			
D.6 Packing					
Expected Result	Result	Actual Finding / Comments			
What is the number of corrugated layers on cartons? (1 Corrugated layer=3ply) Single Wall Corrugated (3 Ply) Double Wall Corrugated (5 Ply)	DOUBLE WALL CORRUGA TED				
Products are perfectly fitted in the carton: (no over-packed, no gap, no crash are allowed)	2 double wall corrugate d cartons are used.				
Outer packing					
Expected Result	Result	Actual Finding / Comments			
	ok	20pcs/export carton			
Dimensions of export carton	· · · ·				



L	
W	

ok	L: 23cm x W: 18.5cm x H: 22.5cm
ok	L: 27cm x W: 18.5cm x H: 22.5cm
ok	L: 27cm x W: 18cm x H: 22.5cm
ok	L: 23cm x W: 18.5cm x H: 22.5cm

Pictures of cartons dimensions check:



Weight of Cartons


Expected Result		Result	Actual Finding / Comments		
Less than 20kg/carton		ok	14KG		
Less	Less than 20kg/carton		14KG		
Less	than 20kg/carton	ok	16KG		
Less than 20kg/carton		ok	16KG		
D.7 Shipping mark					
Expected Result Result			Actual Finding / Comments		
CSDP Gadgetonline - Imaginars srl DESCRIPTION: Reggillbro Civetta Rosso ODS/SAP=931461/PIN412 CSDP order: 4172 QTY/CARTON: CARTON MEAS.: C/NO: / MADE IN: P.R.C.		Mark with colored picture	CSDP Gadgetonline – Imaginars sel DESCRIPION: Regulibre Civetta Rosso ODS/SAT=93146/JPI012 CSDF order-4172 CYV-CARION-20 Partice Control Control CARION (IEAC) 2518.5422.5CM CARION (IEAC) 2518.5422.5CM CNRC 050		
		-			
E.SAMP	LE COLLECTION	-			




F. TESTS AND SPECIAL REQUIREMENTS						
Client's important instruction	s on Tests	Actual Finding / Commo	ents			
Test description	Test description size		Result			
No gap as marked .	30pcs	Comments from Inspector	Passed			
Weight Test						
	30pcs		Passed			
Thickness Test						
	30pcs		Passed			
Size Test						
120*119*200MM		120*119*200MM				
120mm		P 3 4 5 6 7 8 9 m 1	Passed			



	3 4 5 6 7 8 9 W1 2 3 4 5 6 7 8 9 W1	Passed
	0 x 3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9 0 0	Passed
172*119*200MM	172*119*200MM	
172mm	OP 34 5 6 7 8 9 1 2 34 5 6 7 8	Passed
		Passed
	2 3 4 5 6 7 8 9 1 2 3 4 5 6 7 8 9 1 1	Passed
127*119*200MM	127*119*200MM	







G. WORKMANSHIP (DEFECTIVE LIST)				
Client's important instructions on AQL	Actual Finding / Comments			

		CRI	МАЈ	MIN	PICTURE
Corner Damage	MAJ	0	2	0	
OPP bag broken	MIN	0	0	3	
Color Card Missed	MIN	0	0	3	MADE IN CHINA



Bubble	MAJ	0	4	0			
H. WORKMANSHIP SUMMARY							
		CRI	MAJ	MIN	AQL RESULT		
	defectives and	0	6	6			
Maximum allowed		0	10	14	Within AQL		
No. of inspected samples		500	500	500			

I. ADDITIONAL PICTURES



Changing cartons



New cartons















IMPORTANT NOTES

THE ABOVE RESULT(S) REFLECT(S) LANCE GROUP LIMITED'S FINDINGS AT THE TIME AND PLACE OF INSPECTION. THIS REPORT DOES NOT RELEASE THE BUYER OR SELLER FROM CONTRACTUAL RESPONSIBILITIES, NOR DOES IT PREJUDICE THE BUYER'S RIGHT OF CLAIM TOWARD THE SELLER/SUPPLIER FOR COMPENSATION FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING INSPECTION OR OCCURRING ANYTIME THEREAFTER.

THE END OF REPORT